DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

45th 2/01/14

PRINTED: 12/18/2013 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION
A. BUILDING 01 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

445228

B. WING

12/16/2013

NAME OF PROVIDER OR SUPPLIER

LIFE CARE CENTER OF GREENEVILLE

STREET ADDRESS, CITY, STATE, ZIP CODE 725 CRUM STREET

GREENEVILLE, TN 37743

		GREENEVILLE, TN 37743		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 029 SS=D	One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1	K 029	 a) All facility maintenance personnel were immediately in-serviced on NFPA 101 Life Safety Code Standards on 12/16/13. b) Conduit penetration in the main electrical room was sealed with fire rated caulk on 12/16/13. a) All facility residents and visitors have the potential to be affected. b) 100% of facility was checked and no further areas of concern were found on 12/18/13. 	2/1/14
K 062 \$\$=E	This STANDARD is not met as evidenced by: Based on observation and interview, it was determined hazardous area 's one (1) hour fire rated construction is maintained. The findings include: Observation and interview with the Maintenance Director, on December 16, 2013 at 10:30 a.m. confirmed the main electrical room had conduit penetrations that were not fully firestopped in the ceiting. This finding was verified by the Maintenance Supervisor and acknowledged by the Administrator during the exit conference on December 16, 2013. NFPA 101 LIFE SAFETY CODE STANDARD Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5		 a) All facility maintenance personnel were immediately in-serviced on NFPA 101 Life Safety Code Standards on 12/16/13. b) The Maintenance Director, and/or the Maintenance Assistant, will do audits to monitor compliance weekly for 4 weeks and monthly for 2 months. 4) a) Director of Maintenance will present results of audits to the Performance Improvement Committee. b) The Performance Improvement Committee Consisting of Executive Director, Director of Nursing, Medical Director, Director of Rehabilitation, Director of Health Information, Dietary Manager, Director of Maintenance, Director of Environmental Services, Director of 	

BORATORY DIRECTOR'S OF PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

<u>xeoutive</u> Director

TITLE

(X6) DATE

by deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that her safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days lowing the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 ys following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued ogram participation.

(X1) PROVIDER/SUPPLIER/CLIA

STATEMENT OF DEFICIENCIES

PRINTED: 12/18/2013 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY

COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A, BUILDING 01 - MAIN BUILDING 01 445228 12/16/2013 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 725 CRUM STREET LIFE CARE CENTER OF GREENEVILLE **GREENEVILLE, TN 37743** PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION DATE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) Social Services, Business Office Manager, Activities Director, and K 062 Continued From page 1 Staff Development Coordinator will review the results. If it is deemed This STANDARD is not met as evidenced by: necessary by the committee, Based on observation and interview, it was additional education may be determined sprinkler system was not maintained. provided, the process The findings include: evaluated/revised, and/or the audits 1. Observation and interview with the reviewed for 3 months or until 100% Maintenance Director on December 16, 2013 at compliance is achieved. 10:40 a.m. confirmed four (4) of eight (8) sprinkler heads in the kitchen were corroded 1) a) All facility maintenance personnel 2/1/14 K062 (NFPA 25, 5.2.1.1.1.) were immediately in-serviced on 2. Observation and interview with the NFPA 101 Life Safety Code maintenance director, in the corridor, on Standards on 12/16/13. December 16, 2013 at 1:30 p.m. wiring above the lay in ceiling was attached to or supported by b) 1) The 4 of the 8 corroded sprinkler piping (NFPA 13, 6-1.1.5) above the sprinkler heads in the kitchen will be ceiling in the attic space in the following locations: replaced on 1/10/14. a. The Birch side of the sunroom. b. The Birch side in the attic space by the MDS 2)The wiring above the lay in the Office. ceiling will be corrected and not c. Conduit was supported by sprinkler piping by attached or supported by the sprinkler the central supply room. piping by installing supports in the These findings were verified by the Maintenance attic Birch side of the sunroom, Birch Supervisor and acknowledged by the side by the MDS office, and by the Administrator during the exit conference on central supply room to be completed December 16, 2013. by 1/10/14. 2) a) All facility residents and visitors have the potential to be affected. b) 100% of facility was checked and no further areas of concern were found on 12/30/13. 3) a) All facility maintenance personnel were immediately in-serviced on NFPA 101 Life Safety Code Standards on 12/16/13.

(X2) MULTIPLE CONSTRUCTION

)RM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 7DGE21

Facility ID: TN3004

If continuation sheet Page 2 of 2